

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY CMI INTOXILYZER 5000 MAINTENANCE REPORT

RECEIVED OHSS BINN ANNA Program
By Carol Day at 8:00 am, Mar 15, 2010

79665-	
Complete this report in duplicate at the time of the regular monthly preve instrument is repaired. Send copy to Department of Health; Retain original in d	
INTOXILYZER 5000 SN	DATE OF INSPECTION
6605020	03105/2010
LOCATION OF INSTRUMENT (STREET AND CITY)	TIME OF INSPECTION
1/109 Hickman Mills. Kansas City Mo	0220 hours
Place a check (✓) to left of each item if found to be satisfactory or if operating values where determined.) Unchecked items must be corrected before using in	
DVM TEST: (.350 +/150)	
DIAGNOSTIC CHECK (PRINTOUT ATTACHED) Passad	Constitution of the Property of the Constitution of the Constituti
CHARACTER DISPLAY TEST PUSSED	
PRINT TEST (PRINTOUT ATTACHED) Passed	
\boxtimes TIME AND DATE $Passed$	
CALIBRATION CHECK- Run three tests using a standard solution. All three tests must be with have a spread of .005 or less. Check the box corresponding to the standard CHECK MODE) (PRINTOUT ATTACHED) ○ 0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.10 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.0 (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE RE	andard solution being used. (USE CAL. 05% INCLUSIVE 42% INCLUSIVE
TEST 1	TEST 3 . 098
SIMULATOR TEMPERATURE (34° +/2°C) 34.0 DIGILLS CO	
PERFORM RFI TEST (PRINTOUT ATTACHED) Pass/d	
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NIN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TEST	
REFUSALS 4 004 2 .0509 / .1014 2	.1519 5 Over .19 Ø
List any new parts and describe any alteration or modification that was m satisfactorily and within established limits (use other side if necessary).	ade to restore the instrument to operate
Breath instrument tested and certified	within Missouri
Department of Health guidelines.	
Buth Laboratories Inc., Lot#9270, Fxp.	ires 09/23/10,.10 Solution
INSPECTING OFFICER	
SIGNATURE	PRINT NAME
P.O. EJAUM // 1MO, 4898	Dawk Minor
TYPE II PERMIT NUMBER/EXPIRATION DATE	ALL ALGA GALLS
MO 580-1355 (9-94) AN EQUAL OPPORTUNITY/AFFIRMATIVE ACTION EMPLOYER services provided on a nondiscriminatory basis	8/6-482-8/42 LAB-64
and the state of t	



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 09270 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1207 percent (w/vol) ethyl alcohol. The expiration date for this lot number is September 23, 2010 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.10 percent BAC.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC. 50-80-805026 E235-23 TRANCID TEST TRAIDITED - RET 83/85/2816 82:22 11103 HICKMAN HILLS DR SPD 1NTOXILYZER - ALCOHOL ANALYZER HO HODEL 5000 SN 66-005020 03/05/2010

DIAGNOSTIC TEST

02:16

PROM CHECK E735, 23 PASSED
RAM CHECK PASSED
TEMP CHECK PASSED
PROCESSOR CHECK
SYNC PULSE PASSED
SYNC SPEED PASSED
NEG STABILITY PASSED
REF RANGE PASSED

DIAGNOSTIC

PASSED

PRINTER CHECK
ABCDEFGHIJKLMNOPGRSTHUWXYZ
0123456789

Sh 66-995026 6235, 23

03/95/2010 02:17

ABCDEFGHIJKLMNOPORSTUUMXYZ2123456783 ABCDEFGHIJKLMNOPORSTUUMXYZ012345678310##abcde ABCDEFGHIJKLMNOPORSTUUMXYZ012345678310##abcde 所居工口产厂品出工厂工厂工厂工厂工厂工厂 ABCDEFGHIJKLMNOPORSTUUMXYZ012345678319##abcde 11109 HICKMAN MILLS DR SPD INTOXILYZER - ALCOHOL ANALYZER MO MODEL 5000 SN 66-005020 03/05/2010

TEST	%BAC	TIME
AIR BLANK	.000	02:18
CAL, CHECK	. 098	02:19
AIR BLANK	. 000	92:19
CAL. CHECK	. 096	92:29
AIR BLANK	. 600	02:20
CAL, CHECK	. 098	02:20
AIR BLANK	. 898	92:21

NO REI PRESENT

SUBJECT NAME	
LOCATION OF TEST	

OFFICER'S SIGNATURE & SERIAL NO. Form 123 P.D. (8-91) SUBJECT NAME

LOCATION OF TEST

OFFICER'S SIGNATURE & SERIAL NO. Form 123 P.D. (8-91)

State of Missouri DEPARTMENT OF HEALTH





Lab. 4 (R7-88)

DAWN MINOR

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

INTOXILYZER 5000 for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986. John of Mathewson Date 02/18/09 Director of State Public Health Laboratory Number **9200**30 02/18/2011 Expires Director, Department of Health MO 580-0771 (7-88)